Date: User: Customer Job Number This Issue Prsht Rev. First Issue Written By Comment Job Number: Seq. #:

Thursday, 6/1/2006 10:37:10 AM

Linda Lacelle **Process Sheet Drawing Name** : PAD : CU-DAR001 Dart Helicopters Services : 27325 **Estimate Number** : 11205 **Part Number** : D31957 :110 P.O. Number S.O. No. : 1/1A : 6/1/2006 : D3195 REV A **Drawing Number** : N/A Project Number : NA : SMALL /MED FAB Type **Drawing Revision** AIH: : 26337 Material **Previous Run** : 6/8/2006 Qty: 50 Um: Each **Due Date** Checked & Approved By New Issue 05-12-05 JLM : Est Rev:A **Additional Product** Description: **Machine Or Operation:** Neoprene 1/8" thick D3195 1.0 Comment: Qty.: 0.0197 sf(s)/Unit Total: 0.9870 sf(s)Make from D3195 Neoprene 1/8" thick Material:Neoprene 1/8" thick 06.06.0 Batch: SMALL & MEDIUM FAB RESOURCE 1 2.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Cut & Punch as per Dwg D3195 INSPECT WORK TO CURRENT STEP 3.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 4.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 5 DOCUMENT CONTROL 5.0 Comment: DOCUMENT CONTROL Inspection Level 21 CLOCE 08117 Job Completion

Page 1

Form: rprocess


Dart Aerospace Ltd


| | | | | WORK ORDER CHANGES | | | | | | | | |
|------|------------------|------------|--|--------------------|---------------------------------|---|--|--|--|--|--|--|
| STEP | PROCEDURE CHANGE | Ву | Date | Qty | Approval Mfg / Design Mgr | Approval QC Inspector | | | | | | |
| 2 | TO 37/55-7 | | obobo 1 | 50 | 45142 | 06,06 | | | | | | |
| | | | į | | | | | | | | | |
| | 2 | TO 73/55-7 | CUT D3195-7 PAD SO THAT IT IS FLIGH WITH EDGES OF D3195-3 BRACKET TRANSFER LKATION OF \$0.221 HOLES FROM D3195-3 TO 73195-7 (see D5 cmc, 1 attacky) | TO 3195-7 | T6 73/55-7 | 2 Cut D3195-7 PAD SO THAT IT IS FLISH WITH EDGES OF D3195-3 BRACKET TRANSFER LKATION OF \$0.221 HOLES FROM D3155-3 BLOW 60.06.6) PUT DO 33195-7 | | | | | | |

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | | |
|------|------|----------------------------------|-----------------------------|--------------------------------|----------------|--------------|------------------------|--------------------------|--|
| DATE | | Description of NC | Corrective Action Section B | | | Verification | A | A ======1 | |
| | STEP | Section A | Initial Design Mgr | Action Description Design Mgr | Sign & Date | Section C | Approval Design Mgr | Approval QC Inspector | |
| | | | | | | | · | | |
| | | | | | | | | | |
| | - ' | | | • | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| Part No: | PAR #: | Fault Category: | NCR: | Yes No DQA: | Date: <u>66.09/17</u> |
|----------------------------------|--------|-----------------|------|-----------------|-----------------------|
| NOTE: Date & initial all entries | | | | QA: N/C Closed: | Date: |







D3195-5 & D3195-7 PAD

1) MATERIAL: 60 DUROMETER NEOPRENE 1/8" THICK (POSSIBLE SUPPLIERS, ACCURATE RUBBER)

- 2) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 3) ALL DIMENSIONS ARE IN INCHES

Copyright @ 2003 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Chris Provencal

From:

David Shepherd [dshepherd@dartaero.com]

Sent:

June 1, 2006 3:34 PM

To:

'Chris Provencal'

Subject:

RE: D3195 pad change

Obviously, this is an acceptable deviation.

David

----Original Message----

From: Chris Provencal [mailto:cprovencal@dartaero.com]

Sent: Thursday, June 01, 2006 1:16 PM

To: davids@dartaero.com Subject: D3195 pad change

David,

The D3195-5/-7 Pads should be 2.50" long instead of 2.720". Sylvie showed me the parts and I agree.

If made to drawing they are too long. In the past they've done them to fit the brackets (2.50" long and making the holes by transfering the location from the brackets).

For this batch they should have a signed-off change to the work order. I will instruct them to cut the length to be flush with the bracket and transfer the location of the hole from the D3195-1/-3 brackets. Is this change OK?

I will measure some of the final parts to update the dwg.

Sincerely,
Chris Provencal
DART Aerospace Ltd.
Email..cprovencal@dartaero.com
Phone...613-632-3336
Fax......613-632-4443